



211320110362



检测报告

TEST REPORT

No. 2024MS-W0507

样品名称 雨刮器刮片
Name of Sample

型号规格 808 24"
Type & Specification

送检单位 厦门昶顺汽车配件有限公司
Client



厦门市产品质量监督检验院

XIAMEN PRODUCTS QUALITY SUPERVISION & INSPECTION INSTITUTE

注 意 事 项

REMARKS

1. 报告无本单位“检验检测专用章”无效，涂改无效。

This report is invalid if there is not the mark of special stamp for test report and invalid if altered.

2. 复制报告未重新加盖本单位“检验检测专用章”无效。

The copy of this report is invalid if it is not resealed by the special stamp of our institute.

3. 报告无主检人、审核人和批准人签名无效。

This report is invalid if there are not the marks of the stamp of tester, proofreader and approver.

4. 对报告若有异议，应于收到之日起十五日内向本单位提出。

If there is any objection for this report, please raise it to our institute within 15days after receiving this report.

5. 客户送样的委托检验（检测）结果仅适用于本单位所接收到的样品。

For the entrusted sample test, the test results shown in the report are only applicable for the samples supplied directly by client and accepted by our institute.

6. 若无特别说明，委托单位、生产单位及样品的相关信息未经本单位确认。

The information of client, manufacturer and samples are not confirmed by our institute unless otherwise stated.

7. 未经本单位允许，委托单位不得擅自使用检测数据进行不当宣传。

The test results are not allowed to be published inappropriately without permission.

8. 不在资质认定范围内的项目，其检测结果仅作为科研、教学或内部质量控制之用。

The test results are only used for scientific research, teaching or internal quality control, if the test items of this report are not in the scope of qualification accreditation.

院本部实验室地址（Add）：福建省厦门市湖滨南路170号
(No.170, Hubin South Road, Xiamen, Fujian, China)

电话（Tel）：（0592）2699777 2699778 传真（Fax）：（0592）2699776

邮政编码（Post Code）：361004

翔安实验室地址（Add）：福建省厦门市翔安产业区翔星路88号育成中心

(Incubation Center, No.88, Xiangxing Road, Xiang'an Industrial Zone, Xiamen, Fujian, China)

电话（Tel）：（0592）2699700 传真（Fax）：（0592）2699701

邮政编码（Post Code）：361115

集美实验室地址（Add）：福建省厦门市集美区环美北路259号

(Number 259, Huanmei North Road, Jimei, Xiamen, Fujian, China)

电话（Tel）：（0592）2699722 传真（Fax）：（0592）2699722

邮政编码（Post Code）：361023

网址（Website）：www.xmzjy.org

电子信箱（E-mail）：xmzjyyws@xmzjy.org



厦门市产品质量监督检验院 检测报告

No.2024MS-W0507

第 1 页 共 2 页

产品名称	雨刮器刮片	型号规格	808 24"	
检验类别	委托检测	商 标	/	
标称生产单位	/	生产日期	/	
样品来源	送检单位	厦门昶顺汽车配件有限公司	批（编）号	/
	联系人/ 送样人	刘学添	样品等级	/
	联系地址	/	样品数量	2支
	联系电话	13779922926	送样日期	2024/12/17
	邮政编码	/	报告日期	2024/12/27
样品状态	试验前样品外观正常，符合试验要求。			
检测依据	QC/T 44-2009 汽车风窗玻璃电动刮水器			
检测项目	见续页			
检测时间	2024-12-17 ~ 2024-12-26			
检测说明	/			
主送单位	厦门昶顺汽车配件有限公司	实验地点	集美实验室	

批准：

杨毅梅

审核：

金磊磊

主检：

黄达伟

厦门市产品质量监督检验院

检测报告

No. 2024MS-W0507

(续页)

第 2 页 共 2 页

序号	检测项目	技术要求	检测结果
1	一般要求	刮水器在正常工作状态下, 摆动应均匀, 不应出现抖动现象。	刮水器刮片在正常工作状态下, 摆动均匀, 未见抖动现象。
2		胶条表面应光滑, 无伤痕、裂纹, 刮刀平整、无缺口。	刮水器刮片的胶条表面光滑, 未见伤痕、裂纹, 刮刀平整、未见缺口。
3		可拆卸的刮片和刮杆连接应坚固可靠, 拆装方便。	可拆卸的刮片和刮杆连接坚固可靠, 拆装方便。
4		金属件必须经防腐蚀处理, 或使用具有耐腐蚀性的材料制造。电镀部分镀层应均匀, 不应露出基底, 无明显裂纹和其他有害缺陷。	刮水器刮片的金属件可见防腐蚀处理。电镀部分镀层均匀, 未见露出基底, 未见明显裂纹和其他有害缺陷。
5		金属件油漆层、塑料喷涂层应均匀, 无气泡、堆积、流挂现象。	刮水器刮片金属件油漆层、塑料喷涂层均匀, 未见气泡、堆积、流挂现象。
6	性能要求	刮刷初期整个刮刷范围内应能刮净, 不出现刮刷残痕。	刮水器刮片在刮刷初期整个刮刷范围内能刮净, 未见刮刷残痕。
7	刮刷效果	刮刷循环 50×10^4 次后, 整个刮刷范围内应能刮净, 允许有宽度在0.5mm以下、呈丝状的极细线刮刷残痕3条, 宽度在1.0mm以下、呈丝状的较细线刮刷残痕1条。	刮水器刮片刮刷循环 50×10^4 次后, 整个刮刷范围内能刮净, 宽度在0.5mm以下、呈丝状的极细线刮刷残痕不大于3条, 宽度在1.0mm以下、呈丝状的较细线刮刷残痕不大于1条。
注: 1#样品用于一般要求检测项目; 2#样品用于刮刷效果和耐久性检测项目。			



样品照片

(从左到右分别为1#样品和2#样品)

————— 以下空白 —————